



Incident Number (Fire Dept)	Incident Date & Resolution Time	Incident Type	Hazardous Material Released	Address	Discharge to MS4? (Y/N) If Yes, Which Water Body?	Agency Enforcement Action Required? (Y/N)	Amount Spilled (gal)	Pre & Post Spill Clean-up Pics Taken? (Y/N)	Report Synopsis	Responsible Party
F221010	10/10/2021 ± 3 hours	Vehicle accident	Hydraulic	Cody Road and Howell's Ferry Intersection	N	N	<10-15	Y	MFR Haz Mat team responded to a semi-truck tanker that had flipped as a result of an accident on 10/10/21 at approximately 8 AM. The tanker was filled with several thousand gallons of hydraulic and flipped into a roadside ditch. MFR Haz Mat contained an approximate 10-15 gals of hydraulic that spilled from the truck. No material leaked from the tanker. USES was contracted by the RP to abate the spill 10-15 which was cleaned with oil-dri and scrubbing. Area was abated by 11:30 AM. Post Spill inspection conducted on 10/10/2021 at 11:45 AM.	Operator Company Name - SNL Logistics Cleanup performed by USES
N/A	11/16/2021 ± 5 hours	Hydraulic spill from busted line	Hydraulic Material (30 gallons)	Old Shell Road and Florida Street Intersection	N	N	<30	Y	Waste Management had a garbage truck bust a line that created a hydraulic spill of no more than 30 gallons of material onto City streets (11/16/21). MPD provided traffic control and the City Public Works department secured the scene with sand as no environmental contractor was readily available at the time of the spill. Oil Recovery was hired by WM to abate the spill and the spill was abated by approximately 2 PM on 11/16/21. Post Spill Inspection conduct on 11/16/2021 at 2:30 PM.	Operator Company Name - Waste Management Cleanup performed by Oil Recovery
FY22129	12/9/2021 ± 3 hours	Paint	Paint	HomeDepot	Y	N	Possibly around 5-20 gallons	Y	MFRD HAZ MAT received an emergency call and responded on 12/9/21 at approximately 8:30 PM and witnessed a paint spill/runoff from a HomeDepot store. Contacted City Environmental and requested assistance. Inspected the area and property on 12/9/21 at approximately 9 PM and noted a paint spill coming from building due to rain event. RP was identified as Bella Painting, LLC from Dallas, GA. Due to the amount of rain, no abatement was possible. An MOT was issued to the RP on 12/10 and review of the incident and BMPs for painting was discussed with the RP and HomeDepot management.	Operator Company Name - Bella Painting, LLC
F2203310075	3/31/2022 ± 7 hours	Commercial Vehicle Fire	Diesel	Zeigler Blvd & Schilinger Rd	Y	N	± 45	Y	MFRD received an emergency call regarding a commercial vehilce fire and responded on 3/31/2022 at approximately 3:30PM. Saddle tank on commercial vehicle ruptured and spilled diesel on Zeigler Blvd and nearby stormwater inlet. City Environmental responded and USES was retained for remediation. USES cleaned Zeigler Blvd and nearby inlets. Cleanup efforts were complete at approximately 10:30pm.	Operator Company Name - Vulcan Materials Cleanup performed by USES
F2204190033	4/19/2022 ± 4 hours	Transformer	Petroleum	Ari Ct.	N	N	± 20	Y	MFRD received an emergency call regarding a private vehicle accident on 4/19/2022. The accident resulted in a nearby transformer rupturing. MFRD directed the flow away from a nearby inlet. City Envrionmental responded to assist. APCo. Retained Oil Recovery Co, to remediate the transformer oil.	Cleanup performed by Oil Recovery, Co



Incident Number (Fire Dept)	Incident Date & Resolution Time	Incident Type	Hazardous Material Released	Address	Discharge to MS4? (Y/N) If Yes, Which Water Body?	Agency Enforcement Action Required? (Y/N)	Amount Spilled (gal)	Pre & Post Spill Clean-up Pics Taken? (Y/N)	Report Synopsis	Responsible Party
F2205230092	5/24/2022 ± 12 hours	Commercial Vehicle Spill	Kymene	512 South Washington Ave	Y	N	± 50	Y	MFRD received a call on 5.23.22 from a nursing home due to a concern for residents safety regarding a chemical spill on a neighboring property. City Environmental investigated the property on 5.24.22 and discovered the spill on both private property and City ROW. Responsible party could not be found in an appropriate timeframe. E3 Environmental was retained by the City to remediate the impacts to the City ROW. Cleanup efforts were complete at approximately 9pm.	Operator Company Name - Tightness Transportation,LL C Cleanup performed by E3 Environmental